

TATENT

UNITED STATES PATENT AND TRADEMARK OFFICE

Inventor:

Stephen W. Haines

Patent No.:

4,832,685

Issued:

May 23, 1989

For:

FLUID FLOW CONTROL SYSTEM

AND CONNECTING FITTING

THEREFOR

Docket No.:

M02 41829

CERTIFICATE

MAY 2 4 1999

OF CORRECTION

REQUEST FOR CERTIFICATE OF CORRECTION

CERTIFICATE OF MAILING

I hereby certify that this correspondence is being deposited with the United States Postal Service on the date shown below with sufficient postage as first class mail in an envelope addressed to the: Assistant Commissioner for Patents, Certificate of Correction Branch, Washington, DC 20231.

Date: May 13, 1999

May 10, 1999

444 South Flower Street, 19th Floor

Los Angeles, California 90071-2909

Assistant Commissioner for Patents Certificate of Correction Branch Washington, DC 20231

FOR THE COMMISSIONER OF PAT & TA

Laura A. Brown

05/18/1999 SSANDAR1 00000010 4832685 01 FC:145 10

clerical or typographical nature or of a minor character in the claims which should be corrected.

These errors are found in the application as filed by Applicant. Accordingly, enclosed is a checkfor \$100.00 for payment of the fee as required by 37 C.F.R. § 1.20(a). Please charge any

for \$100.00 for payment of the fee as required by 37 C.F.R. § 1.20(a). Please charge any additional required fees or credit overpayment to Deposit Account No. 16-2460. A duplicate copy of this sheet is enclosed.

In Claim 13, lines 19-20, "pressure relief fluid conduit" should read --pressure-sensitive transducer--.

In Claim 22, line 13, "pressure relief fluid conduit" should read --pressure-sensitive transducer--.

It is evident after a review of the specification and drawings as filed, especially column 7, lines 41-49 and Fig. 3, that "pressure-sensitive transducer" was intended. The errors now sought to be corrected were clearly inadvertent and the correction of these errors does not involve new matter or require reexamination. Accordingly, a Certificate of Correction is requested.

The proposed Certificate of Correction correcting such errors is enclosed.

It is believed that the issuance of a Certificate of Correction is necessary to correct these errors. However, if the Patent and Trademark Office rules that a Certificate of Correction is not required, it is requested that this letter be entered into the patent file and the patentee(s) so notified.

Respectfully submitted,

Robert A. Schroeder

Registration No. 25,373

(213) 622-7700 Enclosures

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 4,832,685

DATED :	May 23, 1989	
NVENTOR(S):	Stephen W. Haines	•
It is sometimed the		
creby corrected	at error appears in the above-identified patent and that said Letters Patent are as shown below:	
At Column 9, Lin eadpressure-se	es 19 and 20, the portion of claim 13 reading "pressure relief fluid conduit" should ensitive transducer	
-pressure-sensitiv	ne 13, the portion of claim 29 reading "pressure relief fluid conduit" should read	
		_
··		
	4.	

BEST AVAILABLE CORY